

### **REASONS FOR ALLOWANCE**

The following is an examiner's statement of reasons for allowance: The subject matter of the independent claims could either not be found or was not suggested in the prior art of record. The subject matter not found in claim 1 was a catheter with a guidewire lumen and an inflation lumen formed by two reinforcing members, wherein the first reinforcing member is a generally tubular and has first and second edges as well as the outer surface of the first member seated against the second interior surface of the catheter shaft, the second reinforcing member is curved and has first and second opposing surfaces, and wherein the second member is disposed on the first and second edges of the first reinforcing member such that the inflation lumen is formed by the inner surface of the tubular first reinforcing member and the first surface of the second curved reinforcing member, and the opposing second surface of the second curved reinforcing member forms a part of the guidewire lumen, in combination with the other elements of the claims.

The subject matter not found in claim 6 was first and second reinforcing members within a catheter, the first reinforcing member having a partial annular cross-section, the first and second members being mechanically coupled together so as to form a fluidly-sealed inflation lumen, and the first and second reinforcing members having different wall thicknesses, in combination with the other elements of the claims.

Any comments considered necessary by applicant must be submitted no later than the payment of the issue fee and, to avoid processing delays, should preferably

accompany the issue fee. Such submissions should be clearly labeled "Comments on Statement of Reasons for Allowance."

Any inquiry concerning this communication or earlier communications from the examiner should be directed to LAURA C. SCHELL whose telephone number is (571)272-7881. The examiner can normally be reached on Monday-Friday 9am-5:30pm.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Kevin Simons can be reached on (571) 272-4965. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see <http://pair-direct.uspto.gov>. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

/Laura C Schell/  
Examiner, Art Unit 3767  
/Kevin C. Simons/  
Supervisory Patent Examiner, Art Unit 3767